

In reply please quote: S93/0103

Mr Peter Patroni, AM
Kinetic Technology International Pty Ltd
1 Kembla Street
CHELTENHAM EAST VIC 3192


Dear Mr Patroni

I recently received a report from Bob Greenwood, Flying Operations Inspector Moorabbin District Office, regarding an assessment he conducted to examine the enhancements to your Aero-Guidance Mk 5 and Mk 6 synthetic trainers.

This letter is to advise that, as a result of that report and in accordance with the conditions of the original approval certificates for the Mk5 and Mk6 versions, the software changes to the device are approved by the Authority. Forthwith any device which incorporates the approved changes is deemed to be approved in accordance with the respective original certificate.

To properly reflect the change of business ownership in this case, amended certificates are enclosed.

Yours faithfully


B J Diamond
District Flight Operations Manager
Moorabbin District Office

22nd December 1994



ICAO — 50th ANNIVERSARY

First Avenue
Moorabbin Airport Vic 3194 Australia

PO Box 20
Cheltenham Vic 3192 Australia

Telephone (03) 339 2666
Facsimile National (03) 586 6197
Facsimile International + 61 3 586 6197